ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M117177
Date Received: 08/02/07
Date Extracted: 08/07/07
Date Analyzed: 08/07/07
Matrix: Water
Units: ug/L (ppb)

Client: Project: Lab ID: Data File:

Alaskan Copper Works PO# M117177, F&BI 708038

708038-01 x10 708038-01 x10.065

Instrument: ICPMS1 Operator: HR

Internal Standard: Germanium

% Recovery: 103

Lower Limit: 60

Upper Limit: 125

Concentration
Analyte: ug/L (ppb)

Chromium 302

 Nickel
 199

 Copper
 202

 Zinc
 <10</td>

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 08/07/07
Date Analyzed: 08/07/07
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: PO# M117177, F&BI 708038
Lab ID: I7-278 mb
Data File: I7-278 mb.038
Instrument: ICPMS1
Operator: HR

Internal Standard: Germanium % Recovery: 102

Lower Limit: 60

Upper Limit: 125

Concentration
Analyte: ug/L (ppb)

Chromium <1
Nickel <1
Copper <1
Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 08/09/07 Date Received: 08/02/07

Project: Metro Self Monitor, PO# M117177, F&BI 708038

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 708064-19 (Duplicate)

	is will satisfy		Sample	Duplicat	Relative e Percent	Acceptance
VĮ.	Analyte	Reporting Uni	ts Result	Result	Difference	Criteria
	Chromium	ug/L (ppb)	3.18	3.57	12	0-20
	Nickel	ug/L (ppb)	2.62	2.99	13	0-20
	Copper	ug/L (ppb)	1.99	2.13	7	0-20
	Zinc	ug/L (ppb)	8.48	8.19	3	0-20

Laboratory Code: 708064-19 (Matrix Spike)

		Spike	Sample	Percent Recover		
Analyte	Reporting Units	Level	Result	MS	Criteria	
Chromium	ug/L (ppb)	20	3.18	102	50-150	TE
Nickel	ug/L (ppb)	20	2.62	94	50-150	
Copper	ug/L (ppb)	20	1.99	95	50-150	
Zinc	ug/L (ppb)	50	8.48	99	50-150	

Laboratory Code: Laboratory Control Sample

		Spike	Percer Recove		e
Analyte	Reporting Units		LCS	Criteria	
Chromium	ug/L (ppb)	20	99	70-130	411
Nickel	ug/L (ppb)	20	98	70-130	
Copper	ug/L (ppb)	20	97	70-130	
Zinc	ug/L (ppb)	50	98	70-130	

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- **a** The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- **b** The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv The sample was diluted due to insufficient sample volume. Detection limits are raised due to dilution
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- fp Compounds in the sample matrix interfered with quantitation of the analyte. The reported concentration may be a false positive.
- **hr** The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- ${f J}$ The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- **nm** The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

August 9, 2007



INVOICE #07ACU0809-1

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO# M117177, F&BI 708038 - Results of testing requested by Gerry Thompson for material submitted on August 2, 2007.

 1 sample analyzed for Total Chromium, Copper, Nickel and Zinc

 by Method 200.8 @ \$80 per sample
 \$ 80.00

 60% rush (4 day) of \$80.00
 48.00

 Amount Due
 \$ 128.00

FEDERAL TAX iD # (b) (6)

708038	rud vissal sookulared issolutel ^a . Ale minu et vegs sookule	tivic, viewellanestronterval stanio e atroné une sur sen	SAM	PLE CHAL	N OF CU	JST(DDY	ouwerld a thinker if 40. Th	ME	- 08	1/02	107			ALY
Send Report To SZRAD Company ALASKAN Address 628 S. 2	SAMPLERS (signature) PROJECT NAME/NO. PO# Metro Self Monitin M/17177					Page #of									
City, State, ZIP Septon City,	e w	1 987	37	REMARKS				1	ANAI	YSES	REQU	10	Dispose Return : Will call	after 30 samples	
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	TT	8270	HFS AF7	1/5				Notes
M 1/7177	01	8/67	1:45	HZO	1					17	1		-		
	. 7											.	,		4

			· · · · · · · · · · · · · · · · · · ·			- H		
			·					
			*					
Friedman & Bruya, Inc.	SIGNATURE		PRINT NAME		COMP	MA	DATE	TIME
3012 16th Avenue West	Relinquenced by:	> GE	RAD Thou	Pour	Acre	,	8-2-07	2:35
Seattle, WA 98119-2029	Received by: W W	- 19	han Pha	in	FeB	T	V	V
Ph. (206) 285-8282	Relinquished by:		31 61					
Fax (206) 283-5044	Received by:						:	
FORMS\COC\COC.DOC							90	

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

August 9, 2007

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on August 2, 2007 from the Metro Self Monitor, PO# M117177, F&BI 708038 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0809R.DOC